Inspection Report

Name of Work	:	Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.
Work Order	:	EE/BTP/BBMP/E-PMT(9490)/WO/197/2013-14 Dated: 21.12.2013.
Agency	:	R. Madhusudhan
B.R. No & Date	:	185/14-15 Dated: 02.07.2014
Bill Amount	:	9,89,077.85
Job Code	:	010-14-000018
P. Code	:	P-1771
Date of Inspection	:	19-09-14

The above said Work pot hole filling in Ward No 10 Doddabommasandra Vidyaranayapura para has been shown by the Concerned AE.

The above said Work has been inspected along with the Concerned AE.

It is observed that the ~~pot~~ pot holes showing the executed Items of Works in the Concerned File of the above said Work has been Verified.

The Measurements are checked by me and it is found Satisfactory

The Work done is Satisfactory

G.M.MUNIYAPPA
B.E.(ELECTRICAL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

152 - BYATARAYANAPURA AC
WARD NAME : 10 - DODDA BOMMASANDRA



Verified

G.M.MUNIYAPPA,
B.E.(ELECTRICAL)
EXECUTIVE ENGINEER(ELEC)
PUBLIC WORKS DEPARTMENT

19/09/16

Zadlas
AE

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Sudha
AE

G.M.NAGESHA
B.E.(ELECTRICAL)
EXECUTIVE ENGINEER(I/C)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Jadhav
AE

B.E.(ELECT.)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Jadhav
AE

C.M.MUNIYAPPA
B.E.(ELECT.&E. (CIVIL)
EXECUTIVE ENGINEER(I/TD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Jadhav
AE

G.M.MUNIYAPPA
B.E (ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Jadhav
AE

B.E.(ELECT),B.E (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Jadhav
AE

G.M.MUNIYAPPA,
B.E.(ELEC'T),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Sadhan
AE

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Sadhan
AE

G.M.MUNIYAPPA,
B.E.(ELECT) B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Sadhan
AE

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Pot Hole Filling in Ward No. 10 (Doddabommasandra), Vidyaranayapura Sub Division.

Jadhav
AE

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT